

Document Type:	Tech Brief
Document ID:	TB022
Last Modified Date:	June 12, 2017

Question:

Some versions of GE Plant Applications (v6.x and v7.0) will not install with the M5 Keyless license by default.

Answer:

When installing GE Plant Applications under these conditions, use this additional registry entry to bypass checks made during the installation process.

- Create the “Add” and “Remove” \*LicenseKey.reg files (see attached page below)
- Install the current version of Proficy Common Licensing
- Attach the M5 key with proper licensing
- Double-click the file “**AddLicenseKey.reg**”.
- Run the installers for PA 6.3.
- Test the installed version to ensure it launches and correctly reads the key file.

*To create the needed files for this tech brief, follow the directions below.*

**Open note pad and copy the below into it; save it as “AddLicenseKey.reg”**

\*\*\*\*\* Everything below here \*\*\*\*\*

Windows Registry Editor Version 5.00

[HKEY\_LOCAL\_MACHINE\SOFTWARE\Wow6432Node\GE Intelligent Platforms, Inc.\Proficy Common Licensing]

[HKEY\_LOCAL\_MACHINE\SOFTWARE\Wow6432Node\GE Intelligent Platforms, Inc.\Proficy Common Licensing\00014.00002.00193.00000]

[HKEY\_LOCAL\_MACHINE\SOFTWARE\Wow6432Node\GE Intelligent Platforms, Inc.\Proficy Common Licensing\00015.00003.00540.00000]

\*\*\*\* Everything above here \*\*\*\*\*

Original Author: Chris Carlins on 6/01/2017
Key Words: #plantapps #licensing #install #Plant #Apps #PlantApps #Licensing #Install
Products: GE Plant Applications – v6.X, v7.0 (issue reporting resolved as of v7.1)
Version History: Original version